



## Analysis of Yukon highways pavement damage caused by permitted overload trucks

<https://library.fpinnovations.ca/en/permalink/fpipub52892>

Author: Bradley, Allan  
Thiam, Papa-Masseck

Contributor: Highways & Public Works, Yukon

Date: March 2020

Material Type: Research report

Physical Description: 43 p.

Sector: Forest Operations

Field: Fibre Supply

Research Area: Transportation Infrastructure


Subject: Highway  
Pavement  
Roads  
Trucks  
Vehicles weight  
FPI TR

Series Number: Technical Report ; TR 2020 n.5

Language: English

Abstract: In publication

### Documents



TR2020N5.PDF

 Read Online

 Download